Oil Field Environmental Incident Summary

Responsible Party: Halliburton

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: PALAHNIUK 1-1H

Field Name: WHITETAIL Well File #: 26369

Date Incident:12/1/2013Time Incident:06:24Facility ID Number:County:BILLINGSTwp:143Rng:99Sec:1Qtr:

Location Description:

Submitted By: Justin Collins Received By:

Contact Person: Justin Collins

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled **Units** Recovered Units Followup **Units** 0 Oil barrels 0 barrels **Brine** 0 barrels 0 barrels Other 2 barrels 2 barrels

Description of Other Released Contaminant:

Frac Gel

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Well site scoria

Action Taken or Planned:

Operations shut down, fluid was vacd up and absorbed with diapers. Contaminated material will be removed at completion of job.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 12/1/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of frac gel during fracking activities was contained on location, according to the report. NDIC retains oversight.